

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE  
NEW DELHI- 110001**

No. F.6/DFS/MS/Ind./2024/SZ/300  
To

Dated: 31.../05.../2024

The Authorized Signatory,  
M/s Intex Technologies, (India) Ltd.,  
A- 61, Okhla Phase- II, New Delhi 110020.

**Sub:** Regarding issuance of Fire Safety Certificate in r/o M/s Intex Technologies, (India) Ltd., located at A- 61, Okhla Phase- II, New Delhi 110020.

Sir,

This has reference with letter received through Outdoor diary no 232 dated 04/04/2024 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 27.05.2024 in the presence of Mr. Anil Kumar Sharma to verify the fire safety measures installed in the building. Accordingly fire safety arrangement were tested / checked and found following observation.

1. Fire Check door closing device found removed.
2. Smoke ventilation system found removed in the basement.
3. First aid hose reel provided but found nonfunctional.
4. Automatic sprinkler system provided but found nonfunctional.
5. Fire fighting Pumps are not on auto mode.
6. Exit signage found removed at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

(ATUL GARG)  
DIRECTOR

DELHI FIRE SERVICE