## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No: F.6/DFS/MS/2024/Hospital/WZ/ 3 29

Dated:

14/06/2024

To,

The Medical Superintendent, Deep Chand Bandhu Hospital, Kokiwala Bagh, Ashok Vihar, Delhi-52.

Sub: - Inspection report in r/o Deep Chand Bandhu Hospital, Kokiwala Bagh Ashok Vihar, Delhi- 110052.

Sir,

As per directions of the Competent Authority, it is submitted you that the surprise inspection of above said Hospital building has been carried out by me on 12.06.2024 to see the compliance of the requisite fire safety measures. Dr. Manoj Singh & Sh. Rajesh Kumar (Supervisor, Electrical) was present at the time of inspection.

Following shortcomings were observed at the time of inspection:-

- 1. 6 m internal road shall be cleared all around the building.
- 2. Width of patient ward door is less than the required width of 2m.
- 3. Electrical shafts are not segregated at some places.
- 4. Provisioning of fire check doors in lift lobbies is under process.
- 5. Smoke ventilation in basement found provided but not functional.
- 6. Detectors found removed at some places.
- 7. MOEFA found provided but not functional.
- 8. PA system found provided but not functional.
- 9. Hose reels nozzle found missing.
- 10. Pressurisation of lift lobby found provided but not functional.
- 11. Pumping system not found in automation.
- 12. DG Pump found provided but not functional.
- 13. Fireman grounding switch found removed.
- 14. Control room panel found under maintenance.

You are advised to rectify the above-mentioned shortcoming under intimation to this department, till than the occupancy of the Building/ Premise in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/ Occupier.

Yours Faithfull

Director

h. 011-23414000