



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**



No. F6/DFS/MS/WZ/2024/ 333  
To,

Dated: 14/06/2024

Sh. Sanjeev Khurana,  
M/s Ishani Enterprises,  
E-368, Bawana Industrial Area,  
Delhi- 110039.

**Sub: - Inspection report in r/o M/s. Ishani Enterprises located at E-368, Bawana Industrial Area, Delhi- 110039.**

Sir,

Please refer to letter no. nil received via outdoor diary no. 2044 dated 24/05/2024 on the subject cited above. In this connection, it is to inform you that the above said industrial building was inspected by the officer concerned by this department on 07/06/2024 in the presence of Sh. Sanjeev Khurana to check the functioning of Fire Safety arrangements provided in the building.

During inspection, it has been observed that the building is comprised of Basement + Ground + 02 Upper Floors. Following shortcomings were observed at the time of inspection:-

1. Fire check door found removed.
2. Smoke management system found removed in basement.
3. First aid hose reel found provided but not functional.
4. Terrace level pump found provided but not functional.
5. Over head water storage tank of 5000 ltrs capacity found against the required capacity of 10,000 ltrs.
6. Exit Signages found removed at some places.

In view of the above shortcomings, the application for renewal of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/ Occupier.

Yours faithfully,

(Atul Garg)  
Director

Delhi Fire Service

Copy to :-

1. The Dy. Drugs Controller/ Licensing Authority, Drug Control department, F-17, Karkardooma, Delhi- 110032.