

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI-HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/School/NDZ/2024/ 347

Dated: 18/06/2024

To,

The Manager, Govt. Girls Sr. Sec. School Rani Garden, Delhi - 110031.

Sub: - Regarding grant of Fire Safety Certificate in r/o Govt. Girls Sr. Sec. School located at Rani Garden, Delhi - 110031.

Sir.

This has a reference to your email dated 03/06/2024, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 10/06/2024 in the presence of Mr. Rajan Kumar (Principal) & Mrs. Poonam (H.O.S.) and observed that building comprised of two blocks, Block – B Ground plus one upper floor & Block – C Ground plus three upper floors.

## Following shortcomings were observed during time of inspection:

- 1. Two staircase of width 1.40 meter & 1.50 meter are provided against requirements of 1.50 meter each in block B. Either width of staircase shall be extended an additional staircase of width 1.50 meters shall be provided.
- 2. Fire Extinguishers not provided in block B.
- 3. All Fire Extinguishers are empty in block C.
- 4. First-Aid-Hose Reel provided but not functional.
- 5. Internal hydrants provided but not functional.
- 6. Fire pump of 450 LPM provided but not functional.
- 7. Overhead tank capacity 10,000 liters not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfo

DIRECTOR

Copy to:-

1. The Dy. Director of Education, B - Block, Yamuna Vihar, Delhi - 110053.

2. The Manager, Govt. Girls Sr. Sec. School located at Rani Garden, Delhi - 110031.