



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No: F.6/DFS/MS/School/2024/WZ/ 373

Dated: 28/06/2024

To,

The Principal,
Sant Gyaneshwar Public School,
G.T.K Road, Khampur, Delhi-110036.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Sant Gyaneshwar Public School, G.T.K. Road, Khampur, Delhi- 110036.

Sir,

This has reference to your application no. SG/06/2024-25 dated 12.06.2024 received via outdoor diary no. 2929 dated 13.06.2024 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 21.06.2024 to see the compliance of shortcomings communicated vide this department letter number F6/DFS/MS/School/2016/1179 dated 06/05/2016. Sh. Mukesh Bhatia (Manager) was present at the time of inspection.

During the course of inspection it was observed that school building is comprised of 02 Blocks (Ground plus Two upper floors & Ground plus Three upper floors). Your request for issuance of FSC is rejected due to the following shortcomings:-

1. The school building is not accessible to fire engines as the road width provided is 2.60 m against the required width of 6 m.
2. Width of staircases found 1.60 m & 1.20 m against the required width of 1.50 m each.
3. First aid hose reels found not provided.
4. Terrace level pump found not provided.
5. Overhead tank of 10,000 ltrs capacity found not provided
6. Exit signage's not provided.

You are advised to rectify the above-mentioned shortcomings under intimation to this department.

Yours Faithfully


(A. Garg)
Director
Ph. 011-23414000

Copy to:-

1. Director of Education, Govt. Of NCT of Delhi, Old Secretariat, Delhi.