

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

C/28

No.F6/DFS/MS/School/NDZ/2024 | 395

Dated: 04/07/2024

To

The Principal,  
Shaheed Bhai Bal Mukund,  
Govt. Sarvodaya Vidyalaya, Shankracharya Marg, Delhi-54.

**Sub:- Regarding issuance of Fire Safety Certificate in r/o Shaheed Bhai Bal Mukund, Govt. Sarvodaya Vidyalaya, Shankracharya Marg, Delhi-54.**

Sir,

With reference to your letter no. SBBM SV/S CM/2024-25/170 dated 06.06.2024 on the subject cited above. In this connection, it is to inform you that the school building was inspected by the officer concerned from this department on 24.06.2024 in the presence of Mr. Jitender Sharma (Estate Manager), and it was observed that **the school building is divided into four blocks** [ground + 03 upper floors (new block), ground + 03 upper floors (old block), ground + 01 upper floor & ground floor only]. During the inspection, following shortcomings still exists which issued earlier also vide letter no. F6/DFS/MS/School/NDZ/2021/513 dated 24/09/2021:-

1. First aid hose reels provided but not functional.
2. Fire pump found not functional.
3. Fire water storage tank was found empty at ground + 03 upper floor (Old block).
4. Exit signages are not adequately provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management.

Yours faithfully,

  
(Atul Garg)  
Director

Delhi Fire Service o/c

Tel: 011-23414000

**Copy to:-**

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.