

No. F6/DFS/MS/School/NDZ/2024/ 379

Dated: 07/07/2024

To,

Mr. Mahesh Bhatt (Manager),
Vidhyanchal Public School
X-79, Gali No. 5, Near Shiv Mandir,
Brahmpuri, Delhi – 110053.

Subject: - Regarding grant of Fire Safety Certificate in r/o Vidhyanchal Public School located at X-79, Gali No. 5, Near Shiv Mandir, Brahmpuri, Delhi – 110053.

Sir,

This has a reference to your email dated 12/06/2024, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 24/06/2024 in the presence of Mr. Mahesh Bhatt (Manager), and observed that building comprised of ground plus two upper floors only.

Following shortcomings were observed during time of inspection:

1. One staircases of width 1.10 meter is provided against the requirement of two having width of 1.50 meters each.
2. The width of corridor is 0.75 meter against the requirement of 1.50 meters.
3. The class room door size is 0.85 meter against the requirement of 1.20 meter.
4. All fire extinguishers found empty.
5. First-Aid-Hose Reel not provided.
6. Fire pump of 450 LPM not provided.
7. Overhead tank of capacity 10,000 liters not provided.
8. Exit signage's not provided in strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR

o/c DELHI FIRE SERVICE

Copy to:-

1. The Dy. Director of Education, B - Block, Yamuna Vihar, Delhi - 110053.