

Copy

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001**

No.F6/DFS/MS/School/NDZ/2024/ 409

Dated: 09/07/2024

To

The Principal,  
Francis Girls Senior Secondary School,  
17, Darya Ganj, New Delhi - 110002.

**Sub:-** Regarding issue of Fire Safety Certificate in r/o Francis Girls Senior Secondary School located at 17, Darya Ganj, New Delhi - 110002.

Sir,

This has reference to your letter outdoor diary no. 2750 dated 10.06.2024 received in this department, on the subject cited above. In this connection, this is to inform you that the school building was inspected by officer concerned from this department on 28.06.2024 in the presence of Mrs. Anusha Singh (In charge) and observed that the building is comprised of ground + 02 upper floors. During the inspection, following shortcomings were observed:-

1. 03 nos. of staircase are provided having width of 1.40 m, 0.95 m & 0.95m respectively against the requirement of 02 nos. of 1.5 m each.
2. Hose reel hose provided only at ground & 1<sup>st</sup> floor (found not functional) against the requirement of 02 nos. at each floor.
3. Fire pump of capacity 450 LPM not provided.
4. Over head water storage tank of 10,000 liters capacity is required exclusively for firefighting.
5. Exit signages are not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management.

Yours faithfully,

  
(Atul Garg)

Director  
Delhi Fire Service  
Tel: 011-23414000

**Copy to:-**

The Director of Education,  
Govt. of NCT of Delhi, Old Secretariat, Delhi.