

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/School/SZ/2024/ 432

Dated: 16/07/2024

To

The Principal, M/s G.L.T. Saraswati Bal Mandir Sr. Sec. School, Nehru Nagar, Ring Road, New Delhi-65.

Sub: Regarding renewal of Fire Safety Certificate in respect of M/s G.L.T. Saraswati Bal Mandir Sr. Sec. School located at Nehru Nagar, Ring Road, New Delhi-65.

Sir,

This has reference to email dated 06.06.2024 on the subject cited above. In this context it is informed that the said building was inspected by the officer concerned of this department on 10.07.2024 in the presence of Mr. Ramesh Kumar (Caretaker) and it was observed that school building is comprised of Two block: Block 1 - Ground + 03 upper floors & Block 2 - Ground + 02 upper floors. During the inspection following shortcoming were observed:-

- 1. Hose reel found non functional
- 2. Down comer system found non functional.
- 3. Overhead tank capacity 5,000 liters shall be provided. Presently only 3,000 liters terrace fire tank is available.
- 4. Fire pump found non functional.

In view of above shortcomings, the application renewal of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

Delki Fire Service

Copy to:-.

1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.