

C-22

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI- 110001

No. F6/DFS/MS/School/2024/SZ/ 436

Dated: 16/07/2024

To,

The Manager,
Sunrise Convent School, D-58/280.
D-Block, Bharat Vihar, Kakrola, New Delhi-110043.

Sub: - Regarding renewal of "Fire Safety Certificate" from fire safety point of view in r/o Sunrise Convent School, D-58/280, D-Block, Bharat Vihar, Kakrola, New Delhi-110043.

Sir,

Please refer to your letter No. received on dated 15.06.2024 through online email Id sunrisconventschooldwarka@gmail.com, on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school building on 08.07.2024 to verify the fire safety arrangements in accordance with the rules. At the time of inspection Sh. Ravi Parkash was present and it was observed that the school building was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/school/2021/SZ/180 dated 03.03.2021 for ground and first floor only but now school building is comprised of ground floor plus three upper floors and have following shortcomings: -

1. Two staircases having width of 1.25 to 1.35 and 1.10 to 1.25 m found provided against requirement of two staircases with width of 1.50 m each.
2. Hose reel found provided but not functional.
3. Terrace fire pump 280 LPM found provided against requirement capacity of 450 LPM.
4. Overhead water storage tank capacity of 1,000 ltrs found provided against requirement capacity of 10,000 ltrs.
5. Exit signage's are provided but not sufficient.

In view of above, the school building cannot be considered for grant of fire safety certificate at this stage Therefore you are suggested to rectify the above said shortcomings under the intimation to this department for further course of action.

Yours faithfully

(Akul Garg)

Director

Delhi Fire Service

Copy to:-

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.