GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/WZ/2024/CC | 174

Dated: 15/07/2024

To,

Ms Ruchika Aggarwal, Plot No. 3, FD-Block, Pitampura, Delhi-110088.

Sub: - Inspection report in r/o M/s. Coaching Centre located at Plot No. 3, FD-Block, Pitampura, Delhi-110088.

Sir,

Please refer to your letter no. Nil received via outdoor diary number 3360 dated 25/06/2024 on the subject cited above. In this connection, it is to inform you that the above said building was re-inspected by the officers concerned of this department on 08/07/2024 in the presence of Sh. Inder to check the compliance of shortcomings communicated vide this department letter No. F6/DFS/MS/2024/WZ/100 dated 16/05/2024.

The status of shortcoming is as under:-

Sr.	Shortcomings	Status
No		
1.	Fire & Smoke doors are not provided in staircase lobbies.	Not Rectified
2.	Width of corridor is less than the required width of 1.5 m	Not Rectified
3.	Ventilation in basement and upper floors is not provided.	Not Rectified
4.	Fire pumps were not on auto mode.	Rectified
5.	Open able window shall be provided at each floor.	Not Rectified
6.	Exit signages are not provided.	Rectified

In view of the above shortcomings, the application for issuance of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the Building/premises in absence of requisites fire safety arrangements shall is at the risk and liabilities of the Owner/Occupier.

Yours faithfully

DIRECTOR

Ph; 011-23414000

7 OKA