

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No. F6/DFS/MS/WZ/2024/ 418

Dated: 24/07/2024

To,

Dr. Ashutosh Gupta (Head of Office), SRHC Hospital, Narela, Delhi- 110040.

Sub: - <u>Inspection report in r/o M/s. Satyawadi Raja Harishchandra Hospital, Plot No. 30, Sec. 7 A, Narela, Delhi- 110040.</u>

Sir,

Please refer to your letter no. F. No.3(212)/SRHCH/H&FW/CT/Fire Service/2011 received via outdoor diary no. 3574 dated 28/06/2024 on the subject cited above. In this connection, it is to inform you that the above said building was re-inspected by the officer concerned by this department on 19/07/2024 in the presence of Sh. S.N. Sharma (Supervisor, Electrical) to verify the compliance of shortcomings communicated vide this department letter No. F6/DFS/MS/WZ/2024/Hospital/WZ/335 dated 15/06/2024.

The status of shortcoming is as under:-

Sr. No	Shortcomings	<b>Q</b>
1.	Internal Road of 6 m found obstructed by new construction.	Status
2.	Door closers of fire check doors found removed.	Not Rectified
3.	Fire check door in basement found broken.	Not Rectified
4.	MOEFA found provided but not functional.	Not Rectified
5.	Hose boxes found without hose pipes.	Rectified
6.	Pumping system not found in auto mode.	Not Rectified
7.	Fire control room and patient registration room shall be separate.	Rectified
	and patient registration room shall be separate.	Not Rectified

In view of the above shortcomings, the application for renewal of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall is at the risk and liabilities of the Owner/ Occupier.

Yours faithfully

Mul Garg)
Director

h. 911-23414000

Copy to:-

1. The Executive Engineer, PWD (Electrical), HMED, North Dr. BSA Hospital, Sec. 6, Rohini, Delhi-110085.