

c/11

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001**

No.F6/DFS/MS/School/2024/ 482

Dated: 30 /07/2024

To

The Principal,  
Navshakti Girls Senior Secondary School,  
11, Vishnu Digambar Marg, Rouse Avenue,  
New Delhi.

**Sub: Regarding issuing of FSC in r/o Navshakti Girls Senior Secondary School  
11, Vishnu Digambar Marg, Rouse Avenue, New Delhi.**

Sir,

This has reference to your letter no. nil dated 28.06.2024, on the subject cited above. In this regard, it is to inform you that the site was inspected by officer concerned of this department on 16.07.2024 in the presence of Mrs. Shazir and the following shortcomings are observed.

1. Alternate staircase of .75 m is not provided.
2. Hose reel arrangements are not provided.
3. Terrace Pump of 450 LPM capacity is not provided.
4. Over head tank of 10,000L liter capacity for fire fighting purpose is not provided.

In view of above, fire safety certificate (FSC) cannot be considered at this stage. Therefore, it is requested to rectify the above shortcomings at the earliest for further consideration in the matter.

Yours faithfully,

  
(Anil Garg)  
DIRECTOR  
Delhi Fire Service

Copy to:-

1. The Director (Education), Govt. of NCT, Old Sectt. Delhi - 54.