

c-52

5

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001**

No. F6/DFS/MS/School/WZ/2024/ 522

Dated: 16 / 08 / 2024

To,

The Manager,  
Smt. Lilawanti Saraswati Shishu Mandir,  
FB, Block, Tagore Garden,  
New Delhi-110027.  
Slssm\_1971@yahoo.in

**Sub: - Regarding Issuance of Fire Safety Certificate in respect of Smt. Lilawanti Saraswati Shishu Mandir, FB, Block, Tagore Garden, New Delhi-110027.**

Sir,

Please refer to your letter No. Letter No. SSMT/TG/2023-24/479 dated 26/06/2024, on the subject cited above. In this connection, it is to inform you that the premises was inspected by officer concerned of this department on 02/08/2024 in the presence of Sh. Ajay Kumar (care taker) to see the functioning of fire safety equipments provided in the building.

During inspection, it has been observed that the above school is running in total two blocks BL-1= ground + one upper floor, & BL-2 = ground + three upper floors in a Building comprised of ground + 1 & ground + 3 upper floors. Fire safety arrangements such as Fire Extinguishers, Hose reels, etc provided. However the following shortcomings were observed.

1. Width of staircases is 1.5mtr & 1.20mtr are provided against requirement of 2X 1.5m each, & alternate staircase not connected with 2<sup>nd</sup> floor.
2. First-Aid Hose reels are provided but not functional.
3. Main fire pump capacity of 450 lpm is provided but not functional.
4. Overhead water storage tank capacity of 10,000 ltr is not provided.
5. Exit signage's are not provided.

In view of above Shortcomings, the application for issuance of Fire safety Certificate is rejected. The licensing issuing authority/statutory authority is requested that premises should not be allowed to run till it provided all necessary fire arrangements.

Yours faithfully

  
(Atul Gang)  
Director

Copy To: - 1. The Directorate of Education old Secretariat, Delhi-110054.

13/8/2024