

c/21

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

Dated: 13/08/2024

No. F.6/DFS/MS/EH/2024/SZ/ 330
To

The Addl. Commissioner of Police,
Lic Branch 1st Floor PS Defence Colony,
New Delhi- 110049

Sub: Regarding issuance of FSC in r/o M/s Staple (A Unit of Scran) located at Plot No M-82,
3rd Floor, GK-2, New Delhi 110048

Sir,

This has reference to your **MHA Portal ID 2024071611085 dated 16/07/2024** on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 06.08.2024 in the presence of Mr. Sangram Singh to verify the fire safety measures installed in the building and observed that the restaurant is running 3rd Floor of the building. Accordingly fire safety arrangement were tested / checked and found following observation.

1. Fire Check door in kitchen not provided at 3rd floor.
2. Electrical panel installed in lift lobby of basement need to be removed.
3. Temporary structures at terrace & Staircase need to be removed.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE