

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

Clor

F6/DFS/MS/WZ/2024/ School 580

Dated: 03/09 /

/2024

The Assistant Engineer, PWD, Sub Division-2, Edu. Elect. Edn. 1 Div. (N), Sec. 16, Rohini, Delhi- 110089.

Sub: -Inspection report in r/o Sarvodaya Co-ed Vidyalaya located at Block-A, Keshavpuram New Delhi- 110035.

Sir,

This is in reference to your e mail id dated 02/08/2024 on the subject cited above. In this connection, it is to inform you that the above said school building was re-inspected by the officer concerned of this department on 24/08/2024 in the presence of Sh. Narender Deswal (Estate Manager) to verify the compliance of shortcomings communicated vide this department letter No. F6/DFS/MS/School/2023/WZ/602 dated 22/12/2023.

The status of shortcoming is as under:-

Sr. No	Shortcomings	Status
1.	Fire Extinguishers not provided.	Rectified
2.	First aid hose reels provided but not functional.	Not rectified
3.	Terrace level pump provided but not functional.	Not rectified
4.	Exit signages not provided.	Rectified

In view of the above shortcomings, the request for issuance of Fire Safety Certificate can't be considered at this stage & rejected. You are advised to rectify the above mentioned shortcomings under intimation to this department for further necessary action in this regard.

Yours faithfully,

Ph. 011-23414000

Copy to:-

- 1. The Director, Directorate of Education, Old Secretariat, Delhi.
- 2. The Principal, Sarvodaya Co-ed Vidyalaya, A-Block, Keshavpuram, Delhi-35.