

## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/GH/2024/SZ/ 559

Dated: 05/09./2024

The Joint Commissioner of Police, Lic/Branch, 1st Floor, P.S Defence Colony, New Delhi 110049

Sub: Regarding issuance of FSC in r/o M/s Hotel Highway Crown Guest House, A-87, NH-8, Mahipalpur Extn., New Delhi 110037.

Sir,

This has reference with MHA Portal ID 2024032103406 Dated 06/08/2024 on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 03/09/2024 in the presence of Mr. Badrinath Goswami. During the inspection, it was observed that the building comprised of Basement + Ground + 03 upper floors. Accordingly fire safety arrangement were tested / checked and found following observation.

- 1. The Fire check Smoke ventilation system not provided in the building as per clause 7.31 of UBBL 2016.
- Smoke management system not provided in upper floor as per clause 7.31 of UBBL-2016.
- 3. First aid hose reel provided but found non-functional.
- 4. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.
- 5. Sprinkler system not working in the basement.
- 6. Internal hydrant not working.
- 7. Terrace level pumps capacity 900 LPM not working.
- 8. Exit signage found removed at some places.
- 9. Kitchen running at part portion at terrace level is not allowed.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

(ATUL GARG

DELHI FIRE SERVICE

Yours fait