

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F-6/DFS/MS/2024/SZ/ 527

Dated: - 12 / 09 / 2024

To

Mr. Dr. Ghanbari (Manager)
M/s Training of Junior Youth Building,
Bahai House of Worship Lotus Temple,
Bahapur Kalkaji New Delhi - 110019.

Sub: -Regarding issuance of fire safety certificate in r/o M/s Training of Junior Youth Building at Baha'i House of Worship Lotus Temple, Bahapur Kalkaji New Delhi

Sir,

This has reference to your letter no nil dated 14/08/2024, received through outdoor dairy no 5339 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 03.08.2024 in the presence of Mr. Jayprakash Ambrale to verify the present status of fire safety measures installed in the building. The fire safety arrangements were tested / checked and found following observations:-

- 1 First aid hose reel provided but found not functional.
- 2 Internal hydrant provided but found not functional.
- 3 Terrace level Fire Pump capacity of 900 LPM provided but found not functional.
- 4 Exit signage found removed.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

(ATUL GARG)
(DIRECTOR

DELHI FIRE SERVICE

Copy to:

1. The Executive Engineer (Bldg Department) Central zone, Jal Vihar Lajpat Nagar, New Delhi 110024.