

d29

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001**

No.F6/DFS/MS/NDZ/School/2024/ 647

Dated: 20/09/2024

To

The Principal,  
Smt. Sushila Devi Lakshmi Girls Sen. Sec. School,  
1991 & 1997, Kucha Chelan,  
Khari Baoli, Delhi - 110006.

**Sub: - Regarding issuance of "Fire Safety Certificate" from fire safety point of view in r/o Smt. Sushila Devi Lakshmi Girls Senior Secondary School, Building No. 1991 & 1997, Kucha Chelan, Khari Baoli, Delhi - 110006. (School ID No. 1208126)**

Sir,

This has reference to email dated 30.08.2024 received in this department, on the subject cited above. In this connection, this is to inform you that the school building was visited by the officer concerned from this department on 09.09.2024 in the presence of Mrs. Raj Rani (Vice Principal) and it was observed that school is comprised of two separate buildings & each building comprised of Ground + 03 upper floors but the school is running at ground + 02 upper floors (each building) only and have been partially complied the shortcomings issued vide letter no. F6/DFS/MS/NDZ/School/2023/04 dated 04.01.2024 except following which is still exists:-

1. Road width is less than required width 6 meter. Hence building is not accessible to fire engine.
2. In building no. 01, one existing staircase is less than 1.5 mtrs., hence additional staircase having width of 0.75 mtr. is required.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/ premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management.

Yours faithfully,

  
(Atul Garg)  
Director  
Delhi Fire Service  
Tel: 011-23414000  
13/9/24

**Copy to:-**

The Director of Education,  
Govt. of NCT of Delhi, Old Secretariat, Delhi.