## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELIII FIRE SERVICE: NEW DELHI- 110001



o. F6/DFS/MS/School/NDZ/2024/ 659

Dated: 26/09/2024

To,

The Principal, Arwachin Bharti Bhawan Senior Sec. School C – Block, Vivek Vihar, Delhi -110095.

Subject: - Regarding grant of Fire Safety Certificate in r/o Arwachin Bharti Bhawan Senior Sec. School located at C – Block, Vivek Vihar, Delhi-110095.

Sir,

This has a reference to your Outdoor dairy No. 5791 dated 29/08/2024on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 19/09/2024 in the presence of Mrs. Saumya Anurup Sharma (Principal) and observed that building comprised of Two Blocks i.e. First block - Basement, ground plus two upper floors & Second block- Ground plus three upper floors.

## Following shortcomings were observed during time of inspection:

- 1. All Fire Extinguishers found empty.
- 2. First-Aid-Hose Reel provided in basement but not functional.
- 3. Automatic Sprinkler System provided but not functional.
- 4. Terrace pumps provided but not functional.
- 5. Overhead tank of 5,000 liters capacity is provided against the requirement of 20,000 liters.
- 6. Exit & floors Signage's not provided in strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully.

(ATUL GARD)
DIRECTOR
CDELHI FIRE SERVICE

## Copy to:-

- 1. The Dy. Director of Education, B Block, Yamuna Vihar, Delhi 110053.
- 2. The Principal, Arwachin Bharti Bhawan Senior Sec. School located at C Block, Vivek Vihar, Delhi 110095.