0113

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/School/SZ/2024/ 657

Dated: - \$6 |09 | 2024

To,

The Principal, Gyan Deep School, C-51, Vikas Nagar, New Delhi- 110059.

Sub: - Regarding issuance of FSC from fire safety point of view in r/o Gyan Deep School located at C-51, Vikas Nagar, New Delhi- 110059.

Sir,

Please refer to your letter No. GDS/01/2023-24 dated 05.08.2024, on the subject cited above. In this connection it is to inform you that the above said school building have been inspected by the officer concerned of this department, in presence of Sh. M.K. Saxena (Manager) on dated 19.09.2024, to check the status of the shortcomings already pointed out by this department vide letter No. F6/DFS/MS/School/2016/SZ/425 dated 12.02.2016. During the course of inspection, it was observed that the shortcomings are not fully complied. This department already issue latter regarding in this matter vide letter No. F.6/DFS/MS/School/2024/SZ/383 dated 04.07.2024.

In view of the above, issuance 'Fire Safety Certificate' cannot be granted at this stage. You are requested to rectify the above-mentioned shortcomings under intimation to this department for taking further necessary action in this matter and running school in absence of requisite fire safety arrangements shall be at the risk & liability of the owner/occupier.

Yours faithfully

Copy to: -

The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi- 110054.

: - for necessary action please.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

E-mail: gargatul@hotmail.com No: F.6/DFS/MS/School/2016/SZ

1425

Ph. 011-26189168

Dated:

12/02/16

To,

The Manager, Gyan Deep School (Regd.), C-51, Vikas Nagar, New Delhi-110059.

Sub: - Regarding issuance of Fire Safety Certificate in r/o. Gyan Deep School (Regd.), C-51, Vikas Nagar, New Delhi-110059.

Sir,

This has reference to your letter No. Nil dated 27.01.2016 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 04.02.2016 to see the compliance of the requisite fire safety measures. Sh. M.K. Saxena (Manager) was present at the time of inspection.

During the course of inspection it was observed that the School building is comprised of ground plus three upper floors. The upper floors are served by single staircase having width 88 to 94 cms. The building is not approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The school building comprised of Ground plus three upper floors does not meet the required norms in the light of Delhi Fire Service Act 2007, and Rule 2010, due to the following shortcomings: -

1. The school building is not approachable to the Fire Fighting Vehicles.

2. The upper floors are served by a single staircase having width 88 to 94 cms instead 150 cms, therefore either 88 to 94 cms staircase width may be increased to 150 cms or an additional staircase having width not less than 75 cms is to be provided.

3. One CO₂ type Fire Extinguishers of 4.5 kg/2.2 kg capacity each and seven ABC type Fire Extinguishers of 04 kg capacity each or WCO₂ type Fire Extinguishers of capacity 09 ltrs each are not provided in the school building.

4. First aid hose reel system is not provided in the school building.

5. Fire pump having capacity 450 LPM is not provided in the school building.

6. Overhead water storage tank of 10000 ltrs capacity is not provided in the school building.

7. Exit signs are not provided in the school building.

Note:- If students are more than 45 double doors may be provided in each class room having width 01 meter.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully,

Dy. Chief Fire Officer Delhi Fire Service

de 2012/10