

c-16

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No: F.6/DFS/MS/Hospital/2024/SZ/ 2261

Dated: 09/10/2024

To,

The Authorized Signatory,  
Kids Clinic India Limited (Cloudnine Hospital),  
WZ-66, Khasra No. 26/4/2/2, Khata Khatoni No. 18/18,  
Manohar Nagar, Keshopur Colony, Outer Ring Road,  
Adjoining Vikaspuri, New Delhi- 110018.

Sub: - Regarding issuance of Fire Safety Certificate in r/o. M/s Kids Clinic India Ltd (Cloudnine Hospital), WZ-66, Khasra No. 26/4/2/2, Khata Khatoni No. 18/18, Manohar Nagar, Keshopur Colony, Outer Ring Road, Adjoining Vikaspuri, New Delhi- 110018.

Sir,

This has reference to your Letter No. Nil dated 09.09.2024, on the subject cited above. In this connection this is to inform you that officers concerned of this department inspected the hospital on 04.10.2024 to verify the fire safety arrangements in accordance with the Rules. At the time of inspection Sh. Naveen (MD) was present and it was observed that the hospital building is comprised of basement, stilt, ground plus three upper floors and have following shortcomings.

1. Fire check doors found not provided at one side of staircase and lift lobby.
2. Ventilation / Smoke Management system found not functional at basement and upper floors. Window should be openable at each floor.
3. Internal hydrant & riser is not provided at one side of staircase. Only Hose reel is provided.
4. Services (Generator, R.O Plant etc.) provided at the terrace are not shown in the plan. So, advised to make correction
5. Inspection ladder for overhead tank & Pump found not provided.
6. Capacity of underground water storage tank could not be ascertained. So, advised to submit detail dimensions of tank.
7. Exit & floor marking Signes found not provided.

Keeping in view of above, issuance of Fire Safety Certificate can-not be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours faithfully,

(Atul Garg)  
Director  
Delhi Fire Service

Copy to:-

1. MS, Nursing Homes, DGHS, Govt of NCT of Delhi, S-1, 3<sup>rd</sup> Floor, School Block, Shakarpur, Delhi-110092.
2. Executive Engineer (Bldg.), MCD, West Zone, Dr. Sahib Singh Varma Nigam Bhawan, Second Floor, Shivaji Enclave, New Delhi-110027.

: - for information regarding use of basement.