



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

C/40



No: F.6/DFS/MS/School/2024/WZ/ 723

Dated: 22/10/2024

To,

The Assistant Engineer,  
PWD Sub-Division 4,  
Edu. Elect. Edn. 1 Div. (N),  
Zakhira, Rama Road, Delhi- 110015.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Govt. Boys Sr. Sec. School (New Building)  
Located at Bakhtawarpur, Delhi- 110036.

Sir,

This has reference to your e mail id dated 03/10/2024 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 14.10.2024 to ascertain the availability and operability of the fire prevention and fire safety measure, Sh. Ram Prakash (Electrician) was present at the time of inspection.

During the course of inspection it was observed that building is comprised of Ground plus three upper floors. Your request for issuance of FSC is rejected as the following shortcomings were observed:-

1. First Aid Hose reels found provided but not functional.
2. Terrace level pump found not provided.
3. Exit signage's found not provided.

You are advised to rectify the above-mentioned shortcoming for taking further action as necessary for issuance of Fire Safety Certificate.

Yours Faithfully

(Ajul Garg)  
Director

Ph. 011-23414000

*See n*  
*2/10*

Copy to:-

1. Director of Education, Govt. Of NCT of Delhi, Old Secretariat, New Delhi.