

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

No. F.6/DFS/MS/NDZ/2024/ 2315

Dated: 18.10.2024

To,

Sh. N.K. Gaur,  
Fire Officer,  
New Delhi Municipal Council,  
Palika Kendra, New Delhi.

**Sub: Request for renewal of fire safety certificate in r/o Shivaji Stadium Complex, New Delhi.**

Sir,

This has reference to your mail id <fo@ndmc.gov.in> dated 20.09.2024, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officers concerned of this department on 11-10-2024 in the presence of Sh. Harender Verma , Fire Officer , NDMC and observed that shortcomings issued earlier vide letter no. F6/DFS/MS/2023/527 dated 16/03/2023 (copy enclosed) has not been completely complied so far. Hence, Fire Safety Certificate (FSC) cannot be renewed at this stage.

Therefore, you are requested to rectify the above shortcomings at the earliest under intimation to this department. Further, the occupancy of building /premises in absence requisite fire & life safety arrangements shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit.

Yours faithfully,

Encl: As above.

(Atul Garg)  
DIRECTOR  
Delhi Fire Service

Copy to:

The Chief Architect, New Delhi Municipal Council, Palika Kendra, New Delhi.

(208)

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No.F.6/DFS/MS/2023/ 527

Dated 16/03/2023

To,

Sh. N.K. Gaur,  
Fire Officer,  
New Delhi Municipal Council,  
Palika Kendra, New Delhi.

**Sub: Request for renewal of fire safety certificate in r/o Shivaji Stadium Complex, New Delhi.**

Sir,

This has reference to your mail id [fo@ndmc.gov.in](mailto:fo@ndmc.gov.in) dated 03/02/23, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 06/03/2023 in the presence of **Sh. N.K. Gaur (Fire Officer)** and the following shortcomings were observed:-

1. Fire check door provided in lift lobby for compartmentation found removed by normal door and Lift lobby also found encroached by erecting office /reception.
2. Smoke Management system in basement found nonfunctional.
3. Detectors are found nonfunctional at some offices and also required to be extended at left out area.
4. Exit signages found inadequate in basement.
5. Lift signage "not to use lift in case of fire" found removed.

Therefore, you are requested to rectify the above shortcomings at the earliest under intimation to this department. Further, the occupancy of building /premises in absence requisite fire & life safety arrangements shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit.

Yours faithfully

(Atul Garg)  
DIRECTOR

Delhi Fire Service

Copy to:-

The Chief Architect,  
New Delhi Municipal Council, Palika Kendra, New Delhi.