

C/26





**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

No. F6/DFS/MS/2024/School/ 717

Dated: 21/10/2024

To

The Chairmen  
Vishwa Manav Hanuman  
Saraswati Shishu Mandir  
Mamurpur, Narela, Delhi- 40

**Sub:** - Regarding issuance of fire safety certificate in r/o Vishwa Manav Hanuman Saraswati Shishu Mandir located at Mamurpur, Narela, Delhi- 110040.

Sir,

Please refer to your letter No- Nil dated 16.09.2024 received in this department vide outdoor dairy no-6525 dated 17.09.2024 on the subject cited above. In this connection this is to inform you that the above mention site was visited by the officer concerned of this department on 03.10.2024 in the presence of Sh. Nidhi Sachar (Principal) was also present at site to check the existing fire safety & means of escape measures. During inspection it has been observed that the education building is comprised of Two Blocks, A Block comprised of Ground Floor & B Block comprised of Ground plus First floor. The observations/ shortcomings made are as under:-

1. There is only one staircase provided width of 1.50m against the requirement of two staircase 1.50m each and both staircases continues from ground to terrace level.
2. First aid hose reel hose is not provided.
3. Terrace level fire pump capacity of 450lpm is not provided.
4. Terrace level fire fighting water tank capacity of 10,000ltr is not provided.

Keeping in view of above, grant of Fire Safety Certificate cannot be considered at this stage & rejected. You are requested to rectify the abovementioned shortcomings under intimation to this department; till such time running of school is at your own risk & responsibility.

Yours faithfully

  
(Atul Gang)  
Director

Ph-011-23414000

Copy to:-

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054. 16/10