



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

e16
DFA+
आजादी का
अमृत महोत्सव

No. F6/DFS/MS/EE/2024/NDZ/349

Dated: 23/10/2024

To,

The Manager,
Topper's Classes Private Limited
1/52, Lalita Park, Laxmi Nagar,
Delhi - 110092.

Subject: - Inspection Report in r/o M/s Topper's Classes Private Limited located at 1/52, Lalita Park, Laxmi Nagar, Delhi - 110092.

Sir,

Please refer to your outdoor diary no. 7035 dated 26/11/2024 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 15/10/2024 and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/NDZ/2024/CC/46 dated 08/06/2024 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclosed: As above


(ATUL GARG)
DIRECTOR
o/c DELHI FIRE SERVICE

Copy to: -

1. The Manager M/s Topper's Classes Private Limited located at 1/52, Lalita Park, Laxmi Nagar, Delhi - 110092.
2. The Commissioner, Municipal Corporation of Delhi, Civic Centre, Minto Road, New Delhi - 110002.



Dated: 08/03/2024

No. F6 /DFS/MS/School/NDZ/2024/CC/46

To,

The Manager,
M/s Topper's Classes Private Limited,
1/52, Lalita Park, Laxmi Nagar, Delhi-110092.

Sub: - Regarding grant of Fire Safety Certificate in r/o M/s Topper's Classes Private Limited located at 1/52, Lalita Park, Laxmi Nagar, Delhi-110092.

Sir,

This has a reference to your Email dated 06.02.2024, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 21/02/2024 in the presence of Mr. Praveen kumar (Manager) and observed that building comprised of Basement (Store) + Ground + 03 upper floors only. (Coaching classes running is First & Second upper floor only).

Following shortcomings were observed during time of inspection:

1. First-Aid-Hose Reel not functionable.
2. Fire pump not functionable.
3. Overhead tank of 10,000 liters capacity is provided against the requirement of 15,000 liters.
4. Exit Signage's not provided.
5. Standby Power Supply not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR

o/c DELHI FIRE SERVICE

Copy to: -

1. The Manager M/s Topper's Classes Private Limited located at 1/52, Lalita Park, Laxmi Nagar, Delhi-110092.
2. The Commissioner, Municipal Corporation of Delhi, Civic Centre, Minto Road, New Delhi.