



No.F6/DFS/MS/Hospital/NDZ/2024/2373

Dated 24/10/2024

To,

Dr. Ajay Aggarwal (Managing Director),
Tirupati Stone Centre Urology & Laproscopy Hospital,
6, Gagan Vihar (Near Karkadi Mor Flyover),
Delhi - 110051.

Subject: - Inspection Report in r/o Tirupati Stone Centre Urology & Laproscopy Hospital located at 6, Gagan Vihar (Near Karkadi Mor Flyover), Delhi - 110051.

Sir,

Please refer to your outdoor dairy no. 5690 dated 27/08/2024 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 18/10/2024 and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/2506/2013/2457 dated 25/10/2013 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

(ATUL GARG)
DIRECTOR

O/C DELHI FIRE SERVICE

(u so)

Copy to: -

1. The Director of Health Services, M.O. I/C Nursing Home Cell, Govt. of NCT of Delhi, F-17, Karkardooma, Delhi- 110032.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

Ph - 23414333 Fax - 23412593 Email - cfohq.dfire@nic.in



No. F6/OFS/MS/2506/2013/2457

Dated 25/10/13

To

Dr. Ajay Aggarwal (Managing Director)
Tirupati Stone Centre, Urology & Laproscopy Hospital,
6, Gagan Vihar, (Near Karkari More Flyover), Delhi-51.

Sub: Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o Tirupati Stone Centre, Urology & Laproscopy Hospital, 6, Gagan Vihar, (Near Karkari More Flyover), Delhi-51.

Sir,

Please refer to your letter dated 12.09.13 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the premises to verify the fire safety arrangements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010. At the time of inspection Dr. Ajay Aggarwal, (MS) was present and it was observed that the premises is comprised of basement ground plus three upper floors has following shortcomings.

1. The width of staircases is 1 m as against the requirement of 2 m.
2. Fire pump having 900 LPM out put is required in place of 450 LPM out put.
3. Over head water storage tank capacity 25,000 liters is required exclusively for firefighting in place 15,000 liters.
4. Lift in the basement made to be segregated by providing lobby plus fire check door or be pressurized.

In view of above, the fire safety certificate cannot be issued. Therefore you are suggested to rectify the above said shortcoming under the intimation to this department for further course of action.

Yours faithfully

(Dr. G.C. Misra)

Chief Fire Officer

Delhi Fire Service

Copy to-

The Directorate of Health Services
M.O. I/C Nursing Home Cell,
Govt. of NCT of Delhi, F-17, Karkardooma, Delhi-32.

24/10/13
26/10/2014