

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELHI FIRE SERVICE: NEW DELIII- 110001

गाजादी वा अमृत महोत्सव

No.F6/DFS/MS/Industrial/SZ/2024/ 635

Dated: 25/11/2024

To

The Executive Engineer (Bldg.)HQ Municipal Corporation of Delhi, 9<sup>th</sup> Floor, Minto Road, New Delhi – 110002.

Ref: - Online ID no. 10067616 dated 19.11.2024

Sub:- Regarding issuance of Fire Safety Certificate in r/o Plot No. 5, Block A, Mohan Co-Operative Industrial Estate, Mathura Road, New Delhi.

Sir,

With reference to the online application I.D. no. 10067616 dated 19.11.2024 on the subject cited above, it is informed that the said building was inspected by a joint team of officers from Delhi Fire Service {namely Sh. Mukesh Verma, DO and Rajesh Kumar Shukla, ADO} and Building department of MCD {namely R. S. Meena, J E(Bldg.), Anil Bansal, A E(Bldg.)} in presence of Mr. Harish Sachdeva (Architect) & Mr. Vinod Gambhir (Building representative) on 19.11.2024. During the inspection it was observed that the building is comprised of Ground + Mezzanine + 02 upper floors following shortcomings were observed from fire safety point of view:

- 1. All staircases are not continuous to the terrace.
- 2. The passage to the rear exit shall not pass through the occupied area at 2<sup>nd</sup> floor.
- 3. Additional staircase from 2<sup>nd</sup> floor terrace to 1<sup>st</sup> floor terrace has not been provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Atal Garg)
Director

Delhi Fire Service

The C