

C-29

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110 001**

No. F-6/DFS/MS/2022/WZ/ 2417

Dated: 22/09/2022

To,

Sh. Ajit Singh Khatri,  
M/s Sushila School of Nursing,  
Gali No. 09, Gautam Colony,  
Safiabad Road , Narela, Delhi-40.


**Sub: -Regarding issuance of Fire Safety Certificate in r/o M/s Sushila School of Nursing located at Gali No. 09, Gautam Colony, Safiabad Road, Narela Delhi-40.**

Sir,

This has reference to your application received through e mail id dated 05.09.2022, on the subject cited above, it is to inform you that above mentioned School site was visited by officers concerned of this department on 09.09.2022 in the presence of Sh. Ajit Singh Khatri to verify the compliance of the shortcomings/ observations already communicated by this department vide letter no. F6/DFS/MS/2022/WZ/1322 dated 08.06.2022 and observed that the shortcomings have not been removed so far.

Keeping in view of above Fire Safety Certificate cannot be considered at this stage and in case of any loss of life and property due to fire and other emergency the entire responsibility will be on you.

Yours faithfully

  
(Ajit Garg)  
Director

Delhi Fire Service



Copy to: -

1. Dy. Health Officer, Civil Line Zone, 16 Rajpura Road, Delhi-110054.

C-27

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F-6/DFS/MS/2022/WZ/ 1322

Dated: 08/06/2022

To,

Sh. Ajit Singh Khatri,  
M/s Sushila School of Nursing,  
Gali No. 09, Gautam Colony,  
Safiabad Road, Narela, Delhi-40.

**Sub:-Regarding issuance of Fire Safety Certificate in r/o M/s Sushila School of Nursing located at Gali No. 09, Gautam Colony, Safiabad Road, Narela Delhi-40.**

Sir,

With reference to your letter no. 1052/SSON/2022 received via outdoor diary number 530 dated 19/04/2022 on the subject sited above. In this connection it is to inform you that above mentioned site was visited by officer concerned of this department on 18.05.2022 in presence of Sh. Ajit Singh Khatri. Your request for issuance of Fire Safety Certificate is rejected as following shortcoming were observed at the time of inspection.

1. Width of Staircase found 1.25 m & 1.22 m against required width of 1.5 m each.
2. Door width found 1.05 m against required width of 1.20 m.
3. Only one staircase is going up to terrace against required 02 nos. of staircase.
4. Over Head Water Tank capacity found 8000 ltrs against required capacity of 10000 ltrs.
5. Exit signage's not provided.

You are requested to apply again after compliance of above mentioned shortcomings.

Yours faithfully

(Atul Garg)  
Director

Delhi Fire Service

OUR

Copy to:-

1. Dy. Health Officer, Civil Line Zone, 16 Rajpura Road, Delhi-110054.