

c/07

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

75
 आजादी का
 अमृत महोत्सव

No. F6/DFS/MS/School/WZ/2024/ 787

Dated: 26/11/2024

To,

The Principal,
 Aggarwal Model School,
 2586, Maharaja Agarsain Marg,
 Tri Nagar, New Delhi-110052.

Sub: - Regarding Issuance of Fire Safety Certificate in r/o Aggarwal Model School Located at 2586, Maharaja Agarsain Marg, Tri Nagar, Delhi – 110035.

Sir,

This is in reference to your letter no. nil, received through Outdoor diary No. 5710 dated 28/08/2024, on the subject cited above. In this connection, it is to inform you that the said building/premises was re-inspected by the officer concerned of this department on 01/11/2024 in presence of Mrs. Babita Gupta (Principal) to see the functioning of fire safety equipments provided in the building.

The Following Shortcomings Status is as under:-

S. no.	Shortcomings	Status
1.	Width of staircases are 1 x 115cm & 1 x 90cm provided against requirement of 1.5 mtr each.	Not Rectified
2.	Width of corridor 90cm is provided against requirement of 1.5mtr	Not Rectified
3.	Door size 90cm x 1 is provided against requirement of 1.20 mtr	Not Rectified
4.	Terrace Pump of 450lpm is provided but not on auto mode.	Not Rectified
5.	Exit Sinages are found removed	Rectified

In view of above shortcomings, fire safety certificate cannot be issuance at this stage & rejected. The occupancy of the building/premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/Occupier. The statutory authority is requested that premises should not be allowed to run till it provide all necessary fire arrangements.

Yours Faithfully,


 (Atul Garg)
 Director

Copy To: -

1. The Director, Directorate of Education, old secretariat, Delhi.

1/c

 22/11/2024