



75  
Azadi Ka  
Amrit Mahotsav

C-18

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F.6/DFS/MS/SGH/2024/SZ/ 668

Dated: 11/12/2024

To

The Joint Resident Commissioner,  
Puducherry House, 3, Sardar Patel Marg,  
Chanakya Puri, New Delhi-110021

**Sub: Regarding issuance of Fire Safety Certificate in r/o "Puducherry House" located at No. 3, Sardar Patel Marg, Chanakya Puri, New Delhi-110021**

Sir,

This has reference to your letter No. RC/PH-ND/Misc./2024-25/271 dated 25/10/2024. In this connection, the premise was inspected by the officer concerned of this department from fire & life safety point of view on dated 22/10/2024 in the presence of Sh. Kirpal Singh (Suptd.). During the course of inspection, the shortcomings observed are as below.

1. Fire Check Door found removed in basement.
2. Escape route in basement found blocked/encroached with office furniture.
3. Automatic detection system found non-functional.
4. MOEFA system found non-functional.
5. Terrace level fire pump found non-functional.
6. Access to UGW storage tank found encroached/blocked.
7. Exit signages found removed at some places.
8. Lift signages found removed.
9. Open space (shaft) along the staircase to be sealed/safeguarded with iron frame (Jali) at each floor from safety point of view.

In view of the above shortcomings, the application for issuance of fire safety certificate is rejected. You are advised to rectify the above shortcomings under intimation to this department for further action in the matter.

Yours faithfully,

(ATUL GARG)  
DIRECTOR

T. No. 011-23414000

Copy to: -

1. The Chief Architect, Department of Architecture & Environs, New Delhi Municipal Council, Palika Kendra, New Delhi-110001