

C-28



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

75
आजादी का
अमृत महोत्सव

No. F6/DFS/MS/School/WZ/2024/ 823

Dated: 11/12/2024

To,

The Principal,
M.C. Primary Co-Ed. Model School,
Located at Rampura, New Delhi-110035.

Sub: - Inspection report in respect of M.C. Primary Co-Ed. Model School, Located at Rampura, New Delhi-110035.

Sir/Madam,

Please refer to your letter no. Nil, received through outdoor diary no. 7484 dated 07/10/2024 of this department, on the subject cited above. In this connection it is to inform you that the was inspected by the officer concerned of this department on 11/11/2024 in the presence of Smt. Meenakshi to see the functioning of the fire safety equipments provided in the building.

During inspection, it has been observed that earlier school is running at ground + one upper floor in a building comprised of Ground plus two upper floors was issued FSC vide letter No. F6/DFS/MS/School/MN/2021/785 dated 27/09/2021. Now second floor is using by other govt. school Fire safety arrangements such as, Fire Extinguishers, Hose reels, Terrace pump etc. are provided. However, following shortcomings were observed: -

1. First Aid Hose reels are provided but not funtional.
2. Terrace fire pump capacity of 450 lpm is provided but not functional.
3. Overhead water storage tank of capacity 10,000 ltrs is not provided.
4. Exit signage's are not provided.
5. Classroom door width is less than the required width (1.20 mt).

In view of above shortcomings, the application for issuance of Fire Safety Certificate is cannot considered at this stage & rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The licensing Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(A.M. Garg)
Director

Copy to:-

1. The Directorate of Education Old Secretariat Delhi - 110054

42
29/12/2024