

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/Industrial/SZ/2024/678

To

Mr. Vinay Kumar Gautam (President), 167, Palika Bazar, Connaught Place, New Delhi-01

Sub: -Regarding issuance of Fire Safety Certificate in r/o Building located at Plot No. 55-B, Tughlakabad Institutional Area New Delhi.

Sir, With reference to the letter bearing outdoor diary no. 9644 dated 27.11.2024, on the subject cited above, it is informed that the said building was inspected officer concerned from this department on 09.12.2024 in the presence of Mr. Vinay Gautam (President) and following shortcomings were observed:

- First Aid Hose Reel found non functional.
- 2. Fire Check found (FCD) found removed.
- 3. Smoke Management System/Exhaust fan in basement found non functional.
- 4. Automatic Fire Detection and Alarm System (ADAS) found non functional.
- 5. Manual Operated Electrical Fire Alarm (MOEFA) system found non functional.
- 6. Automatic Sprinkler System found non functional.
- Internal hydrant system found non functional.
- Fire pump found non functional.
- 9. Overhand tank capacity of 10,000 liters for firefighting has not been provided.

Exit signages found removed.

Standby power supply has not been provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit. Yours faithfully

(tul Garg)

Director elhi Fire Service

1. The Executive Engineer (Bldg.) HQ, Municipal Corporation of Delhi, 9th floor, Civic Centre,

2. The Owner/Occupier/Manager, Building located at Plot No. 55-B, Tughlakabad Institutional

Area New Delhi.