## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/2024/ 694

Dated 12 /2024

To,

The Assistant Engineer (E), PWD, HMED (C), HC-II, LNJP, Hospital, New Delhi.

Sub: Regarding renewal of fire NOC of MAIDS phase I and II, New Delhi..

Sir,

This has reference to your mail id <u>aeehmed2@gmail.com</u> dated 21.11.24, on the subject cited above, it is to inform that the site was inspected by the officers concerned of this department on 13/12/24 in the presence of Mr. Ravi Yadav (J.E) and the following shortcomings were observed during inspection.

1. PA System found nonfunctional.

2. MOEEFA found nonfunctional.

3. Compartmentation is not done in basement, openings (horizontal & vertically) are required to be sealed properly.

4. Pressurization of lift lobby found nonfunctional in basement.

5. Exit signage found removed.

Hence, Fire Safety Certificate (FSC) cannot be issued at this stage due to above shortcomings. Therefore, you are requested to rectify the above shortcomings and re-submit for further consideration in the matter.

Yours hithfull

Della Fire Service

Copy to:

1. The Chief Architect, NDMC, Palika Kendra, New Delhi.