



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2025/Metro/ 04

Dated: 01 / 01 / 2025

To

Sh. Shailendra Kumar (AGM/E&M/RC-1),
Delhi Metro Rail Corporation Ltd at First floor,
Haiderpur Badli Mor Metro Station, Shalimar Bagh,
New Delhi-110088.

Sub: - Regarding grant of fire (NOC)/ fire safety certificate in r/o Burari Metro Station, DMRC Delhi.

Sir,

Please refer to your letter no. DMRC/Elect/PH4/RC-1/DE01/Lot1/Fire NOC/530/4288 dated 11.12.2024 on the subject cited above. In this connection this is to inform you the above mentioned site was visited by the officer concerned of this department on 24.12.2024 to verify the fire safety arrangements installed in the building as per issued fire safety recommendations vide letter of even no F6/DFS/MS/BP/2022/120 dated 17.03.2022. At the time of inspection Sh. Sumit Kumar (AM/Elect.) & Team was also present at site. During the course of the inspection, it is observed that the building is comprised of ground, concourse & platform level. Your request for FSC is rejected under Rule 35 (3) due to following shortcomings.

1. Staircases leading from ground to concourse level are under construction.
2. Exit signage's, floor signage and lift signage's are anywhere not provided.
3. Electrical cables in 'TER' room going through party wall is not sealed.
4. Smoke management system is not provided in UPS room.

Keeping in view of above, grant of Fire Safety Certificate cannot be considered at this stage & rejected. You are requested to rectify the above mentioned shortcomings under intimation to this department; till such time running of metro station is at your own risk & responsibility.

Yours faithfully

(Amit Garg)
Director

30/12/24